





PCB after milling



Removal of unused
copper



Through hole plating
and solder mask



THE RESULT

Any comments or additions are welcome
If needed I can mail the gerberfiles (Extended Rs274)
mail me at: mind@box.nl

